	A Code	JAWAHARLAL NEHRU TECHNOLOGICAL UNIVERSITY HYDER B.Tech II Year I Semester Examinations, November/December - 201 METALLURGY AND MATERIALS SCIENCE	16 ABAD A BAD
	Time	(Common to ME, MCT, MSNT) 2: 3 Hours Max.	Marks: 75
•		This question paper contains two parts A and B. Part A is compulsory which carries 25 marks. Answer all questions in Part Part B consists of 5 Units. Answer any one full question from each question carries 10 marks and may have a, b, c as sub questions.	A A C C C C C C C C C C C C C C C C C C
٠		PART- A	
	(a) (b) (c) (d) (e) (f) (g) (h) (i) (j)	Explain why grain boundaries look darker under the microscope while look brighter. Draw the plane (100). What is lever rule? Differentiate between tool steel and Die steel. Differentiate between annealing and normalizing. Distinguish between peritectoid and eutectoid reactions. Write the composition of cartridge brass: Copper and Al are highly ductile compare to Iron. Why Differentiate between crystallize ceramics and cermet's. Define ceramic and composite.	(25 Marks) The grains [2] [3] [2] [3] [2] [3] [2] [3] [2] [3] [2] [3] [2] [3]
		PART- B	
			(50 Marks)
	2.a) b) 3.a) b)	Write about crystallization of meals. What is the role of grain size on the properties of materials? OR State Hume-Rothery's rules for the formation of substitutional solid solution. How do you determine the Miller Indices? Explain it with suitable example.	
(3.a)	Write about crystallization of meals. What is the role of grain size on the properties of materials? State Hume-Rothery's rules for the formation of substitutional solid solution. How do you determine the Miller Indices? Explain it with suitable example. What is phase rule? Give suitable examples. Draw and explain Isomorphous system.	[5+5] on.
(3.a) b) 4.a)	Write about crystallization of meals. What is the role of grain size on the properties of materials? State Hume-Rothery's rules for the formation of substitutional solid solution How do you determine the Miller Indices? Explain it with suitable example. What is phase rule? Give suitable examples. Draw and explain Isomorphous system.	[5+5] on. e. [5+5] [5+5] id reactions.
	3.a) b) 4.a) b)	Write about crystallization of meals. What is the role of grain size on the properties of materials? OR State Hume-Rothery's rules for the formation of substitutional solid solution How do you determine the Miller Indices? Explain it with suitable examples. Draw and explain Isomorphous system. OR OR Draw the Fe-Fe ₃ C Diagram and label all the points, lines, temperatures and OR Draw neatly the TTT curves for Eutectoid steels. What is east Iron and Classify it and write the properties. Write notes on Al-Cu alloys.	[5+5] on. e. [5+5] [10]
	3.a) b) 4.a) b) 4.a) b) 5. 6.	Write about crystallization of meals. What is the role of grain size on the properties of materials? OR State Hume-Rothery's rules for the formation of substitutional solid solution. How do you determine the Miller Indices? Explain it with suitable example. What is phase rule? Give suitable examples. Draw and explain Isomorphous system. OR Draw the Fe-Fe ₃ C Diagram and label all the points, lines, temperatures and the control of the properties. OR Draw neatly the TTT curves for Eutectoid steels. What is east Iron and Classify it and write the properties.	[5+5] on. e. [5+5] [5+5] id reactions. [10] [10] [5+5]

