	·· ··Answ	ver any THREE Part-B is (MCT, AME, MS questions from Compulsory		Iarks: 75
		PAl	RT- A		40 2015
				3×	
	v the conventional w threads.	representation f	or section in ext	ernal screw threa	nds and internal [10]
3. Drav	ch the various form the sectional views the sectional views are used to connect	ew from the from	nt, and view from	n the side of a c	[10] otter joint with [10]
	v sectional view fi butt joint to join p			ve, of the single	riveted, double
			RT - B		
				(1 × 4	15 = 45 Marks)
	mble all parts of		: :	: :	shown in the
follo	wing Figure and d				
a) ha b) ha	lf sectional view f lf sectional view f	from the front, w from the right an	d	ction,	!!
a) ha b) ha	lf sectional view f	from the front, w from the right an	d	ction,	[45]
a) ha b) ha c) vio	lf sectional view f lf sectional view f	From the front, w from the right and ll dimensions are	d e in mm.		

