JAWAHARLAE NEHRU TECHNOLO		· · · · · · · · · · · · · · · · · · ·	* * * ***	
B.Tech II Year II Semester			CRABAD ^a	: : .
STRENGTH OF M	-	ay - 2010		
(Common to	CE, CEE)			
Time: 3 Hours Note: This question paper contains two parts	A: änd B	Max.	. Marks: 75	:***::
Part A is compulsory which carries 25	marks. Answer all	l questions in	Part A.	* * * * * * * * * * * * * * * * * * *
Part B consists of 5 Units. Answer	r any one full q	uestion from	each unit.	
Each question carries 10 marks and ma	y have a, b, c as s	ub questions.		
PART	- A		(25 Marks)	
PART		* * * * * * * * * * * * * * * * * * * *	*****	****
1.a) A shaft of 20 mm diameter and length	1000 mm is subj	ected to twist	ing moment	
such that θ =0.1 rad. What is the shear s b) A shaft is subjected to twisting mome				
radius of the shaft.	int, show how she	our struitt vari	[3]	
c) What do you mean by Equivalent I different end conditions of the column.		?Mention it		:***::
		**********************	[2].::	****
d) A hollow circular column with D=10 gyration?	o nim and d-80 i	iiii, what is i	[3]	
e) What is the kernel of a section? What			[2]	
f) What is the difference between beam a			[3]	
What do you understand about term Un Define shear center. What is the impor			.[2] [3]	
i) In a thick cylinder subjected to inter				
plane section remains plane after the ap	oplication of interr	nal pressure.	[2]	
j) Take a small element of a thin spherical element.	al shell and show	the stresses ac	cting on this [3]	
	:***:::***	****	: <u></u> : :	****
IG PG PG PART	· B	(5	50 Marks)	
2.a) Derive the equation of torsion from fur	ndamentals.			
(b) Find the power that can be transmitted	l by a 60 mm diai	meter shaft at	160 rpm, if	
the permissible shear stress is 80 N/m	nm ² and the maxi	mum torque		_***:
than the mean torque.		N + + + + + + + + + + + + + + + + + + +	[5+3]	
3. A solid circular steel shaft is required		P at 200 rpm	. Determine	
the diameter of the shaft, if the maxim				
in shaft. The solid shaft is now replace diameter equal to 75% of the external				
of the shaft if it is required to transmit	the same horse po	ower at same	rpm and the	****
maximum shear stress produced is a	also the same. Fi	nd the % sa	ving of the	
material by using hollow shaft in place	of solid shaft.		[10]	
is as as as		********	***	



