B. Tech IV Year I Semester Examinations, December - 2019 ROBOTICS (Common to ME, MSNT) Time: 3 Hours Max. Marks: 75 Note: This question paper contains two parts A and B. Part A is compulsory which carries 25 marks. Answer all questions in Part A. Part B consists of 5 Units. Answer any one full question from each unit. Each question carries 10 marks and may have a, b as sub questions. PART - A (25 Marks) What is the load carrying capacity of the robot? .a) Sketch the work volume of cylindrical robot. b) [3] What is composite rotation matrix? c) [2] What are world coordinates? d) [3] e) What is an arm singularity? [2] What is forward differential motion model? f) [3] What are the parts of pneumatic actuator? g) What is the purpose of rotating wiper in potentiometer? h) [3] i) What is the reason for using a robot in stamping press operation? [2] What are bowl feeders? j) [3] PART - B (50 Marks) What are the present and future applications of robots. What are the common four configurations of a robotic arm? b) [10] 3.a) Describe the various components of an industrial robot. Describe the three types of automation under the category of an industrial robot. b) How the joint coordinates and world coordinates are related? 4.a) Find the matrix transformation of a line which is rotated by 30° to Y axis, followed by b) translation of -5 units on Y axis followed by rotation of 600 to Y axis. [10] 5. Establish the link parameters and find the final transformation matrix for the following 3 DOF manipulator as shown in figure. [10]

AG AG AG AG AG AG AG

AG AG AG AG AG AG AG

6. Discuss the Newton Euler algorithm carried out for the complete dynamic formulation of an n-dof manipulator. [10] The second joint of a SCARA manipulator is required to move from 30° to 150° in 5 sec. Find the cubic polynomial to generate the smooth trajectory of the joint. What is the maximum velocity and acceleration for this trajectory. [10]								
	△ (\$.	Discuss abo	out the principles out any three type	and types of elec OR s of tactile sensor	tric motors.	AG		/
	10		[4+6]					
/	Д(J ¹¹	.a) What are the	e various parts jo ries assembly sys	OR ining tasks where tems	robot is involved	4. AG	[4/6]	1
				ooOoo-	_			
/	AG.	AG	AG	ÅG	AG	AG	AG	F
/	4G	AG	AG	AG	AG	AG	AG	-
/			AG	AG	AG	AG	AG	
1	46	AG	AG	AG	AG	AG	AG	4